

January 9, 2012

Illinois Environmental Protection Agency Permit Section Bureau of Land – #33 P.O. Box 19276 Springfield, Illinois 62794-9276



Re: 2018080001 – Winnebago County Winnebago Reclamation Service Northern and Southern Units Third Quarter 2011 Confirmed Increases

Dear Correspondent:

In accordance with the applicable conditions of the permit, a groundwater monitoring review has been conducted on the third quarter 2011 monitoring results. Parameters indicating "confirmed increases" from the Southern and Northern Units are listed in Tables 1 and 2, respectively.

The sample results from each unit well network have been reviewed pursuant to Condition VIII.13 of Permit No. 1991-138-LF, Modification No. 51. Confirmed increases will be addressed in accordance with Condition VIII.15 of the above referenced permit.

If you have any questions or require further information, please contact Mr. Tom Hilbert at (815) 963-7516. Thank you.

Sincerely,

Teresa N. Sharp

Environmental Scientist

TNS:tns:slm

Enclosures

cc: Tom Hilbert – Rock River Environmental Services
Bernie Schorle – US EPA Region 5



ILLINOIS ENVIRONMENTAL PROTECTION AGENCY SOLID WASTE REPORTING FORM

This form must be used as a cover for the following list of notices and reports required by the Illinois EPA's Bureau of Land, Permit Section. All reports must be submitted to the Illinois EPA's Bureau of Land Permit Section. This form must be used for Solid Waste facilities only. Reporting for Hazardous Waste facilities should be submitted on a separate Hazardous Waste Reporting Form. All reports submitted to the Illinois EPA's Bureau of Land Permit Section must contain an original, plus a minimum of two copies.

Note: This form may NOT be used for any request to modify the permit, sampling or operating procedures. Modification requests must be submitted separately in the form of a permit application.

This form is not to be used with permit applications. Your permit will state whether the document you are submitting is required as a report or an application.

Facility Name: Winnebago Landfill - Northern and Southern Units	Site ID#: 2018080001							
Check one of the following, identifying the contents of your submittal:								
LPC-160 Forms								
Quarterly Groundwater Data	Semi-Annual Groundwater Data							
Quarterly Leachate Data	Semi-Annual Leachate Data							
☐ Annual Groundwater Data ☐ Annual Leachate Data ☐	☐ Biennial Groundwater Data ☐ Biennial Leachate Data							
Allitual Leachaite Data								
Annual Groundwater Flow Evaluation	☐ Well Survey Data							
Well Construction Forms and Boring Logs	☐ Well Abandonment Forms							
Notice of Observed Increase in Groundwater Notice of Intent to Perform Confirmation Procedures (Re-sampling) in Groundwater								
Notice of Confirmed Increase of Groundwater Exceedence from Re-sample								
Notice of Methane Exceedences								
Annual Facility Report (per 35 Ill. Adm. Code 813.504) and Gas Monitoring Report								
Annual Certifications per 35 III. Adm. Code 813.501								
Other (identify): Not to be used for Permit Applications								

LPC-591

Table 1 Winnebago Landfill - South Unit Thrid Quarter 2011 Confirmed Exceedences

Parameter	Units 3rdC)tr11	3rdQtr11re	AGQS	Notes
G22D - Upgradient					<u>-</u>
# Chloride, Dissolved	mg/l	300	300	200	

Note:

^{**} indicates exceedence has previously been addressed and approved as part of either Permit Modification 46 or 51.

[#] Data is currently being collected in order to revise the interwell value for dissolved chloride in accordance with Permit Condtion VIII.26.

Table 2

Winnebago Landfill - North Unit Third Quarter 2011 Confirmed Exceedences

Parameter	Units	3rdQtr11	3rdQtr11re	AGQS	Notes
G09M - Upgradient					
# Specific Conductance (field)	umhos	2900	3340	2386.55	
G51S					
# Specific Conductance (field)	umhos	3730		2386.55	
G52S					
Lead, Dissolved	ug/L	24	17	4	

^{*} indicates GMZ parameter.

^{**} indicates exceedence has previously been addressed and approved by either Permit Modification No. 46 or 51.

[#] indicates exceedence is currently being addressing in pending Application Log No. 2011-451.